## DETAILS OF INSPECTION VIOLATIONS AND CORRECTIVE ACTIONS

NO. LOCATION DESCRIPTION	REF.	POINTS	CRITICAL
1 LIDO DISHWASHING	08	0	No
THE SPRAY HOSE WAS NOT PROTECTED WITH A BACK FLOW PREVENTER.			
2 LIDO DISHWASHING	22	0	No
THE UNDERCOUNTER DISHWASHER HAD BEEN OUT OF ORDER FOR AT LEAST A	A MONTH.		
ACTIONS TAKEN:			
THE UNDERCOUNTER DISHWASHER HAD BEEN REPAIRED AND PRESENTLY IS IN	NORDER		
3 LIDO DISHWASHING	28	0	No
CLEAN RACKS OF UTENSILS WERE STORED AGAINST THE HAND WASH SINK.			
ACTIONS TAKEN:			
NOTED. CREWMEMBERS INSTRUCTED			
4 LIDO BUFFET LINE	19	0	No
THE SNEEZE GUARDS DID NOT PROPERLY PROTECT THE FOOD ITEMS.			
ACTIONS TAKEN:			
THE SNEEZE GUARDS HAVE BEEN CHANGED FOR NEW ONES PROPERLY PROTE	ECT ING THE F	OOD ITEMS	
5 POTABLE WATER	08	0	No
THE INTERNATIONAL SHORE CONNECTION RP'S WERE NOT PRESSURE TESTED	Э.		
6 PEST MANAGEMENT	40	0	No
A WRITTEN PEST CONTROL PLAN WAS NOT PROVIDED.			
ACTIONS TAKEN:			
A WRITTEN INTEGRATED PEST MANAGEMENT PLAN HAS BEEN PROVIDED AND	IS AVAILABLE	FOR USE	
7 MAIN GALLEY	26	3	Yes
SEVERAL SOILED CONDIMENT CONTAINERS WERE STORED AS CLEAN.			
ACTIONS TAKEN:			
NOTED. CREWMEMBERS INSTRUCTED			
8 MAIN GALLEY-WAREWASH AREA	37	0	No
CONDENSATION BUILDUP WAS NOTED ON THE DECKHEAD OVER THE DIRTY EN	ID OF THE WA	REWASH AR	EA.
9 MAIN GALLEY	*	0	No
IT IS STRONGLY RECOMMENDED THAT A BLAST CHILLER BE PURCHASED FOR FOODS PREPARED AND COOLED IN LARGE CONTAINERS.	THE PROPER	COOLING O	F ALL FOODS ESPECIALLY
ACTIONS TAKEN:			
A BLAST CHILLER HAS BEEN PURCHASED, INSTALLED AND IS IN USE			
10 FOOD SERVICE GENERAL	20	2	No
NUMEROUS REFRIGERATORS THROUGHOUT THE GALLEYS ARE NOT PROVIDI HOLDING FOODS. PANS OF ICE ARE BEING STORED IN THE REFRIGERATORS T			
ACTIONS TAKEN:			
THE REFRIGERATORS HAVE BEEN CHECKED, REGARGED WITH FREON AND AD	JUSTED TO PF	ROPER TEMP	PERATURES
11 INTEGRATED PEST MANAGEMENT	39	0	Yes
THREE ROACHES WERE OBSERVED IN THE BAKERY AREA.			
12 FOOD SERVICE GENERAL	21	1	No
SOME NON-FOOD CONTACT SURFACES OF EQUIPMENT CONTAINED GAPS AND FEATURES.	) CREVICES, A	ND OTHER N	ION EASILY CLEANABLE
13 FOOD SERVICE GENERAL	33	1	No
DECKS, BULKHEADS, AND DECKHEADS HAD HOLES, GAPS, LOOSE PROFILE STR	RIPS, AND OTH	IER NON-EAS	SILY CLEANABLE